

SHEET METAL BASKET
INSTRUCTIONS:

1. Make all hems $3/16$ inch.
2. Make all angles 45° .
3. Bend along dotted lines.
4. Handle is to be soldered at center of basket $1\frac{1}{4}$ inches above top edge.

