


Bill of Material

- 2 - 2" x 6" x 8' runners
- 1 - 4" x 4" x 8' legs
- 3 - 2" x 4" x 8' end braces and side braces
- 1 - 2" x 4" x 10' side brace and center support
- 3 - 2" x 8" x 8' sides and ends
- 5 - 1" x 8" x 8' floor

Construction Procedure

1. Cut out runners as shown.
2. Mark and cut out four legs as indicated.
3. Locate legs on runners, square and nail.
4. Measure width of floor boards, sides and legs to determine exact length of box supports. Cut, square and nail to legs.
5. Cut end braces and nail in place, use floor board to determine exact location.
6. Nail in sides, floor and ends.
7. Cut and nail in side braces as indicated.
8. Cut and nail in center box support.
9. Treat with a wood preservative.

FEED BUNK
SCALE - $\frac{3}{4} = 1'-0"$
DATE - 29 MARCH 1967
USED - COURTESY - C.WESTON
DRAWN & TRACED BY - B.W.
DEVELOPED BY - O.BARROW
PLAN NUMBER - 300



SEED BUNK

TOP VIEW

1" X 8" BOARDS

END VIEW

